



**Audit Summary**

Audit Conclusions and General Comments for the client following completion of the audit.

Fire door maintenance seen to have been carried out to a high standard with a well documented system.

**Opportunities For Improvement (OFI)**

Clearly number and identify each OFI separately below. These will be followed up as required at the next audit.

None